Software Release Details

If your software is higher or equal to the versions listed below no action is needed.

Otherwise, please review this bulletin and consider taking actions as suggested.

Component	Version
System Software	061.090.224.30300
Network Controller	061.094.30220
Copy Controller	061.094.24540
UI	061.094.25120
Marking Engine	008.035.000
DADH	012.011.000
C-Finisher	017.019.000
D-Finisher	013.013.000
FAX	003.010.034
Scanner	011.050.008

Purpose

This Bulletin is ONLY intended for the specific security problem(s) identified below. The problem(s) identified has been rated as a criticality level of **IMPORTANT**

- Nessus vulnerability scan indicates CVE-2010-5298 Open SSL exposure.

- Vulnerability in the Bash command line interpreter AKA "Shellshock"

Technical Support Operations

Installation Notes

<u>Firmware Release File</u>

Release Install File	061.090.224.30300 or greater

The SPAR Software and installation notes are located here:

http://www.support.xerox.com/support/workcentre-7755-7765-7775/file-download/enus.html?contentId=107866

Save the file to a convenient location on your workstation. Unzip the file if necessary

Technical Support Operations