30.105.35.000

Software Release Details

If your software is higher or equal to the versions listed below no action is needed.

Otherwise, please review this bulletin and consider taking actions as suggested.

Component	Version
System Software	30.105.35.000
Network Controller	4.02.13
Main Controller	2.50.05.35
UI	0.040.17.005
Image Output Terminal	0.41.69
Document Feeder	1.04

Purpose

This Bulletin is ONLY intended for the specific security problem(s) identified below. The problem(s) identified has been rated as a criticality level of **IMPORTANT**

- OpenSSL vulnerability fix also known as 'man-in-the-middle' (MiTM)

Installation Notes

Firmware Release File

Release Install File	30.105.35.000 or greater

The SPAR Software is located here:
http://www.support.xerox.com/support/workcentre-4250/file-download/enca.html?contentId=102922

Installation Instructions are located at
https://www.xrxgsn.com/admin/public/3452/WC4250Spar.html.

Save the file to a convenient location on your workstation. Unzip the file if necessary.

Technical Support Operations