Mini Bulletin XRX15AU
Xerox® Phaser® 6600 / WorkCentre® 6605
Spar Firmware Release PL3-R1

Release Date: November 11, 2015
Update: November 14, 2019

Purpose

This Bulletin is intended ONLY for the specific security problem identified below. The problem identified has been rated a criticality level of **IMPORTANT**

Includes fix for:

- SSLv3.0 Poodle Vulnerability (CVE-2014-3566). SSLv3 supports an older encryption method that is no longer considered secure, and is no longer viable for protecting sensitive data in transmission over networks. This could allow a Man-in-The-Middle (MiTM) attack where a person on the network can force a "downgrade" of the session between a client and server to use SSLv3 instead of a more secure protocol such as TLS.

To implement the fix, on the SSL page set SSL to 'Enabled' and 'SSLv3' to 'Disabled'.

Software Release Details

If your software is higher or equal to the versions listed below no action is needed.

Otherwise, please review this bulletin and consider installation of this version.

Model	Phaser 6600	WorkCentre 6605
Firmware version	201509031021	201509031026
Link to update	Available here	Available here

Completely unzip the file to a known location on your workstation/computer.

The Installation Instructions for both products are Available here.

xerox