

## Software Release Details

If your software is higher or equal to the versions listed below no action is needed. Otherwise, please review this bulletin and consider taking actions as suggested.

System Software	WC 3315	WC3325
System Software	52.005.25.000	51.005.26.000
Main Controller Board	2.50.04.25	2.50.04.24
Image Output Terminal	1.00.34	1.00.33
Network	4.04.00.08	4.04.00.07

## Purpose

This Bulletin is ONLY intended for the specific security problem(s) identified below. The problem(s) identified has been rated as a criticality level of **IMPORTANT**

- Includes fix for SSLv3.0 Poodle Vulnerability (CVE-2014-3566)

## Installation Notes

The SPAR Software is located as follows:

WC 3315

<http://www.support.xerox.com/support/workcentre-3315-3325/file-download/enca.html?contentId=122833>

WC 3325

<http://www.support.xerox.com/support/workcentre-3315-3325/file-download/enca.html?contentId=122834>

The installation instructions are located at:

<http://www.support.xerox.com/support/workcentre-3315-3325/file-download/enus.html?contentId=122832>

Save the file to a convenient location on your workstation. Unzip the file if necessary

## IMPORTANT – Read before installing Firmware

The “TLS Only” or “Only TLS” checkbox will be enabled by default and will support TLS versions 1.2, 1.1 and 1.0.

- When choosing TLS only – SSL (all versions) are turned off and device is only transferring in TLS 1.2, 1.1 and 1.0.
- When enabling the “Require SSL v3” option, the device will use SSLv3 only to establish a connection.
- The 2 features, “TLS Only” and “Require SSLv3” are mutually exclusive of one another. If one is checked the other must be unchecked. Also, if both features are off (unchecked), the device will use SSL (all versions) and TLS (all versions) simultaneously if needed.