

Software Release Details

System Software	CQ 8700/8900	CQ 93xx	WC 58xx
System Software	072.161.134.32804	072.180.134. 32804	072.190.134.32804
Network Controller	072.164.32802	072.184.32802	072.194.32802
User Interface	072.164.32800	072.184.32800	072.194.32800
Marking Engine	004.004.050	020.011.018	096.065.000
Copy Controller	072.164.32800	072.184.32800	072.194.32800
Document Feeder	010.062.000	025.021.048	110.011.020
Fax	003.011.016	003.011.016	003.011.016
Scanner	030.187.000	040.173.000	002.094.000
Finisher (HVF)	N/A	002.003.097	004.004.003
Finisher (LCSS)	N/A	002.001.007	001.033.000

System Software	WC 7220/7225	WC 7830/7835	WC 7845/7855
System Software	072.030.134.32804	072.010.134.32804	072.040.134.32804
Network Controller	072.034.32802	072.014.32802	072.044.32802
User Interface	072.034.32800	072.014.32800	072.044.32800
Marking Engine	018.001.000	090.029.000	090.079.000
Copy Controller	072.034.32800	072.014.32800	072.044.32800
Document Feeder	012.003.000	012.003.000	007.019.000
Fax	003.011.016	003.011.016	003.011.016
Scanner	010.093.000	004.093.000	008.093.000
Finisher (HVF)	N/A	N/A	N/A
Finisher (LCSS)	N/A	N/A	N/A

System Software	WC 3655	WC 6655	WC 7970
System Software	072.060.134.32804	072.110.134.2804	072.200.134.32804
Network Controller	072.064.32802	072.114.32802	072.204.32802
User Interface	072.064.32800	072.114.32800	072.204.32800
Marking Engine	001.032.000	001.003.000	054.021.000
Copy Controller	072.064.32800	072.114.32800	072.204.32800
Document Feeder	001.002.005	001.002.005	007.019.000
Fax	003.011.016	003.011.016	003.011.016
Scanner	000.000.782	000/000.739	008.093.000
Finisher (HVF)	N/A	N/A	N/A
Finisher (LCSS)	N/A	N/A	N/A

Purpose

This Bulletin is ONLY intended for the specific security problem(s) identified below. The problem(s) identified has been rated as a criticality level of **IMPORTANT**

- Bash Shellshock Vulnerabilities CVE-2014-6271, CVE-2014-7169, CVE-2014-7186, CVE-2014-7187, CVE-2014-6277 and CVE-2014-6278 have been fixed in this release.
- Various SSL and PHP vulnerabilities
- CVE 2014-3505, 2014-3506, 2014-3507, 2014-3508, 2014-3510 Device requires Open SSL version updated to 0.9.8zb or higher

Installation Notes

Firmware Release File

Release Install File	072.xxx.134.32801 or higher
----------------------	-----------------------------

The SPAR Software and installation notes are located here:

[87xx/89XXsoftware](#)

[93xxsoftware](#)

[3655software](#)

[58xxsoftware](#)

[6655software](#)

[72xxsoftware](#)

[7830-35software](#)

[7845-55software](#)

[7970software](#)

Save the file to a convenient location on your workstation. Unzip the file if necessary.