

Mini Bulletin XRX16F Phaser 3300MFP SPAR Release 1.50.00.22

Bulletin Date: Mar 01, 2016



Purpose

This Bulletin is intended **ONLY** for the specific security problems identified below. The problems identified has been rated a criticality level of **IMPORTANT**. This release includes OpenSSL 1.0.2d.

Includes fixes for:

- Logjam Vulnerability in OpenSSL (CVE-2015-0400). A vulnerability in TLS protocol versions 1.2 and earlier allows man-in-the-middle attacks to occur against vulnerable systems that support older key exchange methods. Xerox has included a non-vulnerable version of OpenSSL in the software version available below.
- Fix for VxWorks TCP Sequence (CVE 2015-3963). Wind River VxWorks does not properly generate TCP initial sequence number (ISN) values, which makes it easier for remote attackers to spoof TCP sessions by predicting an ISN value.

Software Release Details

If your software is higher or equal to the versions listed below no action is needed.

Otherwise, please review this bulletin and consider installation of this version.

Model	Phaser 3300MFP
Firmware version	1.50.00.22
Link to Software Release	Available here
Link to Installation Instructions	Available here

Save the file to a convenient location on your workstation. Unzip the file if necessary.